Installation instructions




Termination


STEP 1: Strip off at maxium 0.7 inch of the jacket from end of cable.




STEP 2: Press the wires through the projecting portion of terminals until fixed.The maxium wire length is 0.4 inch.




STEP 3: Insert L-jack into the guide.



STEP 4: Press L-tool to terminate L-jack and cut extra wires.



STEP 5: Place cap on L-jack and press to make sure it is fully seated.



eurolan.com info@eurolan.se

