

INSTRUCTION FOR EASY RJ45


Remove Cable Jacket




Cut the Cross




Arrange the 4PR Wires



After arrangement, cut 2mm away



Assemble Plug by wiremap 568A or 568B



Cut the Balance Wires and Crimping Plug



Completion

