










# A0664 / 500 A0664 / 1000

GB INSTALLATION INSTRUCTIONS.  
IT ISTRUZIONI PER L'INSTALLAZIONE.  
DE MONTAGEANLEITUNG.  
FR INSTRUCTIONS POUR L'INSTALLATION.  
ES INSTRUCCIONES PARA LA INSTALACIÓN.

NL INSTRUCTIES VOOR DE INSTALLATIE.  
PT INSTRUÇÕES DE INSTALAÇÃO.  
DK MONTERINGSVEJLEDNING.  
CZ NÁVOD K INSTALACI.  
PL INSTRUKCJA INSTALACJI.


RU ИНСТРУКЦИИ ПО УСТАНОВКЕ.  
SI NAVODILA ZA MONTAŽO.  
GR ΟΔΗΓΙΕΣ ΕΓΚΑΤΑΣΤΑΣΗΣ.  
SK INŠTRUKCIE K INŠTALÁCII.

הוראות התקנה. **IL**  
تعليمات التثبيت. **SA**



8

## FACTORY WIRED



L

LINE


N

NEUTRAL

G

GROUND

H07RN-F 3G1+2,5 mm<sup>2</sup>  
Ø8,5÷10,5 mm



A




B





C



D



THROUGH WIRING CONNECTION



230 V

Max 100 m

## VERSION

A0664 + GUELL ZERO / 15W / H07RN 3G 1,5mm<sup>2</sup>

## FITTINGS

Max 25

A0664 + GUELL ZERO / 15W / H07RN 3G 2,5mm<sup>2</sup>

Max 41

A0664 + GUELL ZERO / 20W / H07RN 3G 1,5mm<sup>2</sup>


Max 21

A0664 + GUELL ZERO / 20W / H07RN 3G 2,5mm<sup>2</sup>

Max 35

9

CLOSED

1  
2,5 Nm  
(2x)2  
0,8 Nm  
(2x)

OK



GASKET

NO



GASKET